

Temperature and Sensitivity Calibration Protocol

NETZSCH

Software Manual

DSC Instruments

Temperature and Sensitivity Calibration

www.netzsch-thermal-analysis.com

To be explained:

- *Measurement of the calibration substances*
- *Evaluation of the measurements*
- *Creation of a temperature/sensitivity calibration file*

Please note the following additional information for the calibration procedure:

- The measurement conditions (e.g. heating rate, gases, type of crucible) for the calibration measurement and the subsequent sample measurement must be the same.
- Use an empty crucible for the reference position.
- Note all information for using the calibration substances in the provided documentation.

Melting point standards

Can be used for Al₂O₃ crucibles and Pt crucibles with Al₂O₃ liners; C₁₀H₁₆, In, Sn, Bi, Zn also for aluminum crucibles.

Adamantane (C₁₀H₁₆) → for the low temperature range
Indium (In) → most accurate value
Tin (Sn)
Bismut (Bi)
Zinc (Zn)
Aluminum (Al)
Silver (Ag) → melting point depends on oxygen partial pressure
Gold (Au) → very accurate value




For the low temperature range use C₁₀H₁₆, In, Sn, Bi, Zn.
Al, Ag and Au are not applicable to low temperature furnaces.

Standards showing polymorphic transitions

Can be used for Pt crucibles; RbNO₃, KNO₃, KClO₄, Ag₂SO₄ and CsCl also for aluminum crucibles.

Rubidium nitrate (RbNO₃) → only for temperature calibration and one heating step
(not useable for 2nd and 3rd heating)
Potassium nitrate (KNO₃) → only for one heating step
(not useable for 2nd and 3rd heating)
Potassium perchlorate (KClO₄) → only for one heating step
(not useable for 2nd and 3rd heating)
Silver sulphate (Ag₂SO₄) → only for one heating step
(not useable for 2nd and 3rd heating)
Cesium chloride (CsCl)
Potassium chromate (K₂CrO₄) → not applicable to low temperature furnaces
Barium carbonate (BaCO₃) → not applicable to low temperature furnaces
Strontium carbonate (SrCO₃) → not applicable to low temperature furnaces

1. Measurement of the Calibration Substances

	<p>1. Open the NETZSCH-Proteus group.</p>
	<p>2. Select the instrument (e.g. DSC 404 F1).</p>
	<p>3. Select New in the File menu.</p>

Measurement Definition

Setup | Header | Temperature Program | Last Items

Property	Value	
Instrument name	DSC 404F1 (DSC404F1A-0030-01) on USB1-4146	Modify instrument name
Furnace (*)	High Temp Rh S TC: S (0 ... 1650 °C) 50 K/min	<input type="checkbox"/> Fan control disabled
Sample carrier	DSC Cp S TC: S (0 ... 1650 °C)	
Measurement mode	DSC	
Crucible (*)	DSC/TO pan Pt-Rh (... 1700 °C)	Help on crucible selection
Start criteria	7.0 K, Heat.: (20 K/min, 30 min), Cool.: (50 K/min, 300 min)	Modify start criteria
Devices	MFCs	
Special instrument control	None	
STC (*)	Off	
TC calibration (20 °C) (*)	On	
Weighing mode	Manual input	
Temperature limiting dev.	No special device	
Emergency temperature	Enhancement to maximum segment temperature: 10 K	Redefine enhancement

Current hardware temperature range is from 0 °C to 1650 °C

(*) Item has multiple possible values.

Legend
 inputs not complete inputs OK inputs must be verified page cannot be accessed inputs are not necessary

<- Backward OK Measure Cancel Forward ->

4. Measurement Definition

Setup

- Check the instrument setup.
The values of the different properties must be checked and changed (if necessary).
- Click **Forward**.

Measurement Definition

Setup | Header | Temperature Program | Last Items

Measurement type
 Correction
 Sample
 Correction + sample
 Sample + correction

Laboratory: NGB
 Project: calibration
 Operator: RS
 Date: 28.09.2011 09:21:59
 Material:

Sample
 Identity: 01
 Name: Test
 Mass: 10 mg
 Crucible mass: 0 mg

Reference
 Name:
 Mass: 0 mg
 Crucible mass: 0 mg

Device	Value
Purge 1 MFC	ARGON
Purge 2 MFC	ARGON
Protective MFC	ARGON

Change gases

Temperature calibration:
 will not be used
 will be used (selected) Select...

Sensitivity calibration:
 will not be used
 will be used (selected) Select...

Benchmark:
 Enter the name of laboratory


Tau-R calibration:
 will not be used
 will be used (selected) Select...

Legend
 inputs not complete inputs OK inputs must be verified page cannot be accessed inputs are not necessary

<- Backward OK Measure Cancel Forward ->

5. Measurement Definition Header

- Select Measurement Type **Sample**.
Optionally:
Define **Laboratory, Project, Operator, Date** and **Material**.
Define **Identity, Name** and enter the **sample mass**.
- Set the checkmark **will not be used** for temperature calibration and also for sensitivity calibration.
- Define the gas for **Purge 1, Purge 2** and **Protective**.
- Click **Forward**.




Heating rate: depending on the application
(e.g. 20 K/min)
Acquisition rate: 100 Points/min
Cooling rate: select a practicable cooling rate
(depending on the instrument)

6. Measurement Definition Temperature Program


- Enter the temperature program for the first calibration substance.

e.g. Indium (melting point 156.6°C)


Carry out a measurement with 3 sequential heating segments up to 260°C and 2 cooling segments down to 50°C (see figure below). For the evaluation afterwards use only the peak from the 2nd and 3rd heating. See also all additional information on page 6 for a detailed description of the temperature program for each standard!



- Define the gas flow for purge and protective (e.g. purge 50 ml/min, protective 20 ml/min).
- Click **Forward**.




- 7. Define folder and file name and save the measurement.



8. Measurement Definition

Last Items

- The previously selected folder and filename is shown in the window (to change folder and filename once again click the **Select** button).
- Click **Measure**.



9. Start the Measurement

- Push **Set initial gases** (the gas switches are set to the INITIAL start conditions (carried out automatically during preheating/precooling)).
 - Click **Start**.
- If necessary, check the **Instrument Configuration**.

Additional Information for the Temperature Program

- Carry out measurements for all standard materials with 3 heating and 2 cooling segments so that the melting peak is measured three times.
- Depending on the instrument configuration (e.g. furnace type, sample carrier) modify the end temperature of the heating segment (shown as an example in the table below) in such a way that the complete melting peak can be evaluated. Cool down to about 100°C below the melting point.
- For the evaluation use only the values from the 2nd and 3rd heating (both for temperature and sensitivity calibration).


calibration substance	melting point in °C	temperature program (example)
Adamantane (C10H16) (for low temperature range)	-64.5	-120°C to -20°C (heating segment) -20°C to -120°C (cooling segment) -120°C to -20°C (heating segment) -20°C to -120°C (cooling segment) -120°C to 25°C (heating segment) (so that you can open the furnace)
Indium (In)	156.6	20°C to 260°C (heating segment) 260°C to 50°C (cooling segment) 50°C to 260°C (heating segment) 260°C to 50°C (cooling segment) 50°C to 260°C (heating segment)
Tin (Sn)	231.9	20°C to 340°C (heating segment) 340°C to 130°C (cooling segment) 130°C to 340°C (heating segment) 340°C to 130°C (cooling segment) 130°C to 340°C (heating segment)
Bismuth (Bi)	271.4	20°C to 380°C (heating segment) 380°C to 170°C (cooling segment) 170°C to 380°C (heating segment) 380°C to 170°C (cooling segment) 170°C to 380°C (heating segment)
Zinc (Zn)	419.6	20°C to 480°C (heating segment) 480°C to 320°C (cooling segment) 320°C to 480°C (heating segment) 480°C to 320°C (cooling segment) 320°C to 480°C (heating segment)
Aluminium (Al)	660.6	20°C to 760°C (heating segment) 760°C to 560°C (cooling segment) 560°C to 760°C (heating segment) 760°C to 560°C (cooling segment) 560°C to 760°C (heating segment)
Gold (Au)	1064.4	20°C to 1150°C (heating segment) 1150°C to 950°C (cooling segment) 950°C to 1150°C (heating segment) 1150°C to 950°C (cooling segment) 1150°C to 950°C (heating segment)

Heating rate: depending on the application (e.g. 20 K/min)


Acquisition rate: 100 Points/min

Cooling rate: select a practicable cooling rate (depending on the instrument)


2. Evaluation of the Measurements



10. Open the **Proteus Analysis**.




11. Select **Open** in the **File** menu.




12. Open your respective measurement (the measurement file which you have saved under item 7).

Continue with **Open**.




13. Select **X-Temperature** in the **Settings** menu. The temperature is shown on the X axis.


Temperature Calibration



14. Click on the DSC curve for selection. Select **Onset** in the **Evaluation** menu to determine the extrapolated onset.




15. To evaluate the extrapolated onset, define the right and left evaluation limit as shown in the figure and click **Apply**.




16. If the extrapolated onset was determined correctly, click **OK**. If not, it is still possible to change the right and left evaluation limit. To evaluate click **Apply**. If the extrapolated onset was determined correctly, click **OK**.

Write down the determined onset value of the 2nd and 3rd measurement.


Sensitivity Calibration



17. Select **Area** in the **Evaluation** menu.






18. To evaluate the peak area, define the right and left evaluation limit as shown in the figure and click **Apply**.




19. If the peak area was determined correctly, click OK. If not, it is still possible to change the right and left evaluation limit. To evaluate click **Apply**. If the peak area was determined correctly, click **OK**.


Write down the determined peak area of the 2nd and 3rd measurement.

3. Creation of a Temperature/Sensitivity Calibration File

Temperature Calibration	
	<p>20. Open Temperature Calibration in the NETZSCH-Proteus group.</p>
	<p>21. Open Select Instrument in the File menu.</p>
	<p>22. Select your instrument and click OK.</p>




23. Select **New** in the **File** menu.




24. Check the instrument configuration (change if necessary).

Continue with **OK**.




25. Define both the **atmosphere** and the **heating rate** used for the calibration measurements.

Continue with **OK**.




26. Click **Delete** to remove all materials you have not measured.



27. Enter the determined onset values for all calibration materials.

Click **Calculate** to evaluate the curve.

Click **Graph** to see the calibration curve.



28. Check the correct form of the curve. The curve is acceptable if:


- The fitted curve goes through all points.
- **Temp. nom.** and **Temp. corr.** are nearly the same (depending on your requirements, e.g. **Temp. nom. - Temp. corr. ± 1-3 K**).

Temp. nom. °C	Temp. exp. °C	Mathematical Weight	Temp. corr. °C
156,6	158,2	10,000	156,6
231,9	232,8	1,000	231,6
271,4	272,6	1,000	271,6
419,5	419,4	1,000	418,9
660,3	661,3	1,000	660,8
1064,2	1066,8	1,000	1064,1


Temp. nom. **Temp. corr.**

The column **Mathematical Weight** contains the mathematical weighing for the fit. It can be edited for each standard to change the shape of the calibration curve. From all calibration standards Indium can be measured with highest accuracy ⇒ Mathem. Weighing 10.


Click **Table** to change the input or accept the settings.



29. Click **OK** to save the calculation.




30. Select **Save as** in the **File** menu to save the data.




31. Define the file name of the **temperature calibration file** and click **Save**.

Sensitivity Calibration




32. Open **Sensitivity Calibration** in the NETZSCH-Proteus group.




33. Open **Select Instrument** in the **File** menu.




34. Select your instrument and click **OK**.




35. Select **New** in the **File** menu.




36. Check the instrument configuration (change if necessary).
Continue with **OK**.



37. Define both the **atmosphere** and the **heating rate** used for the calibration measurements.
Continue with **OK**.




38. Click **Delete** to remove all materials you have not measured.



39. Enter the determined values for the peak area for all calibration materials.

Click **Calculate** to evaluate the curve.

Click **Graph** to see the calibration curve.



40. Check the correct form of the curve.

The curve is acceptable if the deviation between **Sensit. Calc.** and **Sensit. Exp.** is less than $\pm 3\%$.


Peak Area uV*s/mg	Sensit.Exp uV/mW	Mathem. Weighting	Sensit. Calc. uV/mW
-23,890	0,835	10,000	0,836
-46,900	0,775	1,000	0,765
-38,570	0,728	1,000	0,729
-66,800	0,621	0,800	0,609
-182,500	0,460	1,000	0,471
-22,070	0,346	1,000	0,342

Sensit. Exp


Sensit. Calc.

The column **Mathem. Weighing** contains the mathematical weighing for the fit. It can be edited for each standard to change the shape of the calibration curve. From all calibration standards Indium can be measured with highest accuracy \Rightarrow Mathem. Weighing 10.


Click **Table** to change the input or accept the settings.



41. Click **OK** to save the calculation.



42. Select **Save as** in the **File** menu to save the data.



43. Define the file name of the **sensitivity calibration file** and click **Save**.